
RWY 03 AND 21 SIDS

[USAF] SHL-2100 (RAF)

WADDINGTON, ENGLAND



## V

## DEPARTURE ROUTE DESCRIPTION

RWY 03: SID 03: Climb on rwy track to WAD 3.5 DME. (Cross DER ar or above 266 (35 AGL)) then turn right heading 080° or as directed, to avoid R313 and Wickenby Airfield, contacting Waddinton Departure on 249.85 continuing climb to FL150.

<u>RWY 21: SID 01:</u> Climb on rwy track to 500 (Cross DER at or above 266 (35 AGL)) then turn left to intercept WAD R-192. As soon as possible and before WAD 2 DME turn left track 060° to avoid CRANWELL MATZ, intercept and fly WAD R-080, contact Waddington Departure on 249.85 continuing climb to FL150.

<u>RWY 21: SID 02:</u> Climb rwy track to 500. (Cross DER at or above 266 (35 AGL)) then turn left to intercept WAD R-192. At WAD 3 DME, or 1500, turn right heading 080° or as directed to avoid R313, contact Waddington Departure on 249.85 continuing to FL150.

RADAR REQUIRED

TLv by ATC TA 3000